

Model	Model Year	SOP KW	Engine	Emission	Transmission	Drive	Part Number (TCM)	Calibration ID (Software Version) (TCM)	CVN (Calibration Verification Number) (TCM)	Part Description	Part Number (ECM)	Calibration ID (Software Version) (ECM)	CVN (Calibration Verification Number) (ECM)	Concern	Modification Reason / Technical Bulletin
GTI															
VW GTI	2005	27/04	1.8T I-4 Turbo	LEVI	MQ350-5	2WD	-	-	-		06A 906 032 SK	0020	230864E8		
VW GTI	2005	-	1.8T I-4 Turbo	LEVI	MQ350-5	2WD	-	-	-		06A 906 032 SK	0030	B1BCD707		
VW GTI	2005	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 SL	0020	F2339A76		
VW GTI	2005	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 SL	0030	F7253A01		
VW GTI	2005	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A 906 032 SM	0020	1BC63106		
VW GTI	2005	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A 906 032 SM	0030	4BC78D81		
VW GTI	2005	27/04	1.8T I-4 Turbo	LEVI	AQ350	2WD	09A 927 750 BM	0261	C5AB		-	-	-		
VW GTI	2004	22/03	1.8T I-4 Turbo	LEVI	MQ350-5	2WD	-	-	-		06A 906 032 NK	0003	00F0BAD7		
VW GTI	2004	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 NL	0003	6712879E		
VW GTI	2004	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A 906 032 DL	0006	4203D7F3		
VW GTI	2004	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 DM	0005	72F1527D		
VW GTI	2004	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 GH	0006	3276D629		
VW GTI	2004	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A906032 RN	0001	E4D67D4D		
VW GTI	2004	22/03	1.8T I-4 Turbo	LEVI	AQ350	2WD	09A 927 750 BD	0237	0000339C		-	-	-		
VW GTI	2006	22/05	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	-	-	-		1K0 907 115 B	0010	40D8421F	Engine Does Not Crank	TB # 01-06-05 PT010605 new
VW GTI	2006	-	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	-	-	-		1K0 907 115 B	0020	2AE9FA08		
VW GTI	2006	22/05	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	02E 300 043 C	1115	-		-	-	-		
VW GTI	2006	-	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	02E 300 042 Q	0935	-		-	-	-		
Jetta															
VW Jetta	2005	27/04	1.8T I-4 Turbo	LEVI	MQ350-5	2WD	-	-	-		06A 906 032 SK	0020	230864E8		
VW Jetta	2005	-	1.8T I-4 Turbo	LEVI	MQ350-5	2WD	-	-	-		06A 906 032 SK	0030	B1BCD707		
VW Jetta	2005	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 SL	0020	F2339A76		
VW Jetta	2005	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 SL	0030	F7253A01		
VW Jetta	2005	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A 906 032 SM	0020	1BC63106		
VW Jetta	2005	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A 906 032 SM	0030	4BC78D81		
VW Jetta	2005	27/04	1.8T I-4 Turbo	LEVI	AG 5 f	2WD	09A 927 750 BM	0261	C5AB		-	-	-		
VW Jetta	2004	22/03	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A 906 032 DL	0006	4203D7F3		
VW Jetta	2004	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 DM	0005	72F1527D		
VW Jetta	2004	-	1.8T I-4 Turbo	LEVI	AQ350	2WD	-	-	-		06A 906 032 GH	0006	3276D629		
VW Jetta	2004	-	1.8T I-4 Turbo	LEVI	MQ350-6	2WD	-	-	-		06A906032 RN	0001	E4D67D4D		
VW Jetta	2004	22/03	1.8T I-4 Turbo	LEVI	AQ350/MQ350	2WD	09A 927 750 BD 0237	0237	0000339C		-	-	-		
VW Jetta	2006	08/05	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	-	-	-		1K0 907 115 B	0010	40D8421F	Engine Does Not Crank	TB # 01-06-05 PT010605 new
VW Jetta	2006	-	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	-	-	-		1K0 907 115 B	0020	2AE9FA08		
VW Jetta	2006	08/05	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	02E 300 042 Q	0927	00 00 04 F4		-	-	-		
VW Jetta	2006	-	2.0T I-4 FSI	ULEV II	DQ250 6F	2WD	02E 300 043 C	1120	00 00 0b 91		-	-	-		
Passat															
VW Passat	2005	22/04	1.8T I-4 Turbo	Bin 8	ML285/5HP19	2WD/4WD	-	-	-		4B0 906 018 DQ	0010	46A14A1B		
VW Passat	2005	-	1.8T I-4 Turbo	Bin 8	ML285/5HP19	2WD/4WD	-	-	-		4B0 906 018 DQ	0020	3544229A		
VW Passat	2005	22/04	1.8T I-4 Turbo	Bin 8	5HP19	2WD	3B0 927156 CA	0405	E6C1		-	-	-		
VW Passat	2005	-	1.8T I-4 Turbo	Bin 8	5HP19	2WD	3B0 927156 CA	0506	633C		-	-	-		
VW Passat	2005	-	1.8T I-4 Turbo	Bin 8	5HP19	4WD	3B0 927156 CB	0404	610E		-	-	-		
VW Passat	2005	-	1.8T I-4 Turbo	Bin 8	5HP19	4WD	3B0 927156 CB	0505	A9E7		-	-	-		
VW Passat	2004	22/03	1.8T I-4 Turbo	ULEV I	ML285/5HP19	2WD	-	-	-		4B0 906 018DN	0004	E90A6B07		
VW Passat	2004	-	1.8T I-4 Turbo	ULEV I	ML285/5HP19	4WD	-	-	-		4B0 906 018DP	0002	20E8A04E		
VW Passat	2004	-	1.8T I-4 Turbo	ULEV I	ML285/5HP19	4WD	-	-	-		4B0 906 018DP	0003	F3703102	Update Evap Self test	TB # 01-04-19 PTV010419
VW Passat	2004	22/03	1.8T I-4 Turbo	ULEV I	5HP19	2WD	3B0 927 156AM	1212	13F51		-	-	-		
VW Passat	2004	-	1.8T I-4 Turbo	ULEV I	5HP19	4WD	3B0927156 AQ	1213	1BC8D		-	-	-		
VW Passat	2006	08/05	2.0T I-4 FSI	ULEV II	AQ250 6F	2WD	-	-	-		3C0 907 115 F	0010	31E5C80A		
VW Passat	2006	-	2.0T I-4 FSI	ULEV II	AQ250 6F / ML285	2WD	-	-	-		3C0 907 115 G	0020	0BDBF4A8		
VW Passat	2006	08/05	2.0T I-4 FSI	ULEV II	AQ250 6F	2WD	09G 927 750CJ	0736	4EF30937		-	-	-		
VW Passat	2005	22/04	2.8l V6 5V	LEV I	ML285/5HP19	2WD/4WD	-	-	-		3B0 907 551 DC	0010	AB126C82		
VW Passat	2005	-	2.8l V6 5V	LEV I	ML285/5HP19	2WD/4WD	-	-	-		3B0 907 551 DC	0020	2571E4D9		
VW Passat	2005	-	2.8l V6 5V	LEV I	ML285/5HP19	2WD/4WD	-	-	-		3B0 907 551 DC	0030	F220720C		
VW Passat	2005	22/04	2.8l V6 5V	LEV I	5HP19	2WD	3B0 927 156 CC	0404	8FC8		-	-	-		
VW Passat	2005	-	2.8l V6 5V	LEV I	5HP19	2WD	3B0 927 156 CC	0405	7721		-	-	-		
VW Passat	2005	-	2.8l V6 5V	LEV I	5HP19	2WD	3B0 927 156 CC	0507	91FF		-	-	-		
VW Passat	2005	-	2.8l V6 5V	LEV I	5HP19	4WD	3B0 927156 CD	0404	9A70		-	-	-		
VW Passat	2005	-	2.8l V6 5V	LEV I	5HP19	4WD	3B0 927156 CD	0405	D672		-	-	-		

Model	Model Year	SOP KW	Engine	Emission	Transmission	Drive	Part Number (TCM)	Calibration ID (Software Version) (TCM)	CVN (Calibration Verification Number) (TCM)	Part Description	Part Number (ECM)	Calibration ID (Software Version) (ECM)	CVN (Calibration Verification Number) (ECM)	Concern	Modification Reason / Technical Bulletin
VW Passat	2005	-	2.8l V6 5V	LEV I	5HP19	4WD	3B0 927156 CD	0507	CB74		-	-	-		
VW Passat	2004	22/03	2.8l V6 5V	LEV I	5HP19	2WD/4WD	-	-	-		3B0 907 551 DB	0010	7D4F08CD		
VW Passat	2004	-	2.8l V6 5V	LEV I	5HP19	2WD/4WD	-	-	-		3B0 907 551 DB	0020	25F5DACC		
VW Passat	2004	22/03	2.8l V6 5V	LEV I	5HP19	2WD	3B0 927 156 AT	2222	ECD7		-	-	-		
VW Passat	2004	-	2.8l V6 5V	LEV I	5HP19	2WD	3B0 927 156 AT	2223	6152		-	-	-		
VW Passat	2004	-	2.8l V6 5V	LEV I	5HP19	4WD	3B0927156 BA	2222	106EB		-	-	-		
VW Passat	2004	-	2.8l V6 5V	LEV I	5HP19	4WD	3B0927156 BA	2222	EFD3		-	-	-		
VW Passat	2004	-	2.8l V6 5V	LEV I	5HP19	4WD	3B0927156 BA	2225	11EA1		-	-	-	Trans. Harsh shift correctiv	TB # 01-05-14 PTV010514
Phaeton															
VW Phaeton	2006	22/05	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 DG	0020	603CC58E		
VW Phaeton	2006	-	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 DG	0030	A32B8767		
VW Phaeton	2006	22/05	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	09L 927 760 L	2203	41BAA4A2		-	-	-		
VW Phaeton	2005	22/04	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 DD	0020	6070E030		
VW Phaeton	2005	-	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 DD	0030	BB3FA755		
VW Phaeton	2005	22/04	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	09L 927 760 G	1902	3540940F		-	-	-		
VW Phaeton	2005	-	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	09L 927 760 G	1903	35409894		-	-	-		
VW Phaeton	2004	22/03	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 CS	0010	L5E6PA4G		
VW Phaeton	2004	-	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 CS	0030	L5E6PA2G		
VW Phaeton	2004	-	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	-	-	-		4D0 907 560 CS	0040	L5E6PAGG		
VW Phaeton	2004	22/03	4.2l V8 – 2 bank	LEV I	AL420-6Q	4WD	09L 927 760 C	1003	-		-	-	-		
Touareg															
VW Touareg	2006	22/05	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	-	-	-		4D0 907 560 DF	0010	A4E1DBB6		
VW Touareg	2006	-	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	-	-	-		4D0 907 560 DF	0020	10EC3D0D		
VW Touareg	2006	22/05	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	09D 927 750 DB	0742	DEC4976D		-	-	-		
VW Touareg	2006		3.2L V6	Bin 10	AL600-6Q	4WD	09D 927 750 DS	0893						Improved upshift	TB # 01-05-16 01-05-17
VW Touareg	2005	22/04	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	-	-	-		4D0 907 560 DB	0010	C55DDA41		
VW Touareg	2005	-	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	-	-	-		4D0 907 560 DB	0020	C8DC0668		
VW Touareg	2005	-	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	-	-	-		4D0 907 560 DB	0030	D3E8292F		
VW Touareg	2005	22/04	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	09D 927 750 AQ	0551	CC09336F		-	-	-		
VW Touareg	2005	-	4.2l V8 – 2 bank	Bin 10	AL600-6Q	4WD	09D 927 750 AQ	0580	ED905487		-	-	-		
VW Touareg	2005		3.2L V6	Bin 10	AL600-6Q	4WD	09D 927 750 BA	893						Improved upshift	TB # 01-05-16 01-05-17
VW Touareg	2005		3.2L V6 BAA, BMX	Bin 10	AL600-6Q	4WD					022 906 032FT	6618		Cold Start Misfire, Stumble	TB# 01-05-15
VW Touareg	2004		3.2L V6 BAA, BMX	Bin 10	AL600-6Q						022 906 032 BF	6742		Cold Start Misfire, Stumble	TB# 01-04-15 PTV010415
VW Touareg	2004		3.2L V6 AZZ, BAA	Bin 10	AL600-6Q			564						Harsh 5-4 downshift	TB# 01-04-13
VW Touareg	2004		4.2L V8 AXQ, BHX	Bin 10	AL600-6Q						4D0 907 560 DA	OO40		Rough Idle	TB# 01-05-09
VW Touareg	2004		4.2L V8 AXQ, BHX	Bin 10	AL600-6Q			565						Harsh 5-4 downshift	TB# 01-04-13
VW Touareg	2004		4.2L V8 AXQ, BHX	Bin 10	AL600-6Q	4WD	No Part number	NO Ident	No Ident					Vehicle Hesitates	TB# 10-05-04 PTV010504